	Last Updated: DRAFT					Table 7-1 Outfal		charge Detection	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF_0001	Unnamed trib to Lake Quinsigamond	0												
OF_0002	Unnamed trib to Rawson Hill Brook	0												
OF_0003	Shirley Street Pond	0												
OF_0004	Unnamed trib to Lake Quinsigamond	0												
OF_0005	Unnamed trib to Rawson Hill Brook	0												
OF_0006	Dean Park Pond	0												
OF_0007	Unnamed trib to Dean Park Pond	0												
OF_0008	Unnamed trib to Lake Quinsigamond	0												
OF_0009	Shirley Street Pond	0												
OF_0010	Lake Quinsigamond	0												
OF_0011	Unnamed trib to Rawson Hill Brook	0												
OF_0012	Unnamed trib to Lake Quinsigamond	0												
OF_0013	Unnamed trib to Jordan Pond E of Har	0												
OF_0014	Shirley Street Pond	0												
OF_0015	Shirley Street Pond	0												
OF_0016	Dean Park Pond	0												
OF_0017	Unnamed trib to Lake Quinsigamond	0												
OF_0018	Poor Farm Brook	0												
OF_0019	Shirley Street Pond	0												
OF_0020	Unnamed trib to Hop Brook crossing F	0												
OF_0021	Unnamed trib to Lake Quinsigamond	0												
OF_0022	Mill Pond	0												
OF_0023	Shirley Street Pond	0												
OF_0024	Unnamed trib to Dean Park Pond	0												
OF_0025	Unnamed trib to West Brook	0												
OF_0026	Unnamed trib to Newton Pond	0												
OF_0027	Unnamed trib to Hop Brook crossing F	0												
OF_0028	Unnamed trib to Lake Quinsigamond	0												
OF_0029	Rawson Hill Brook	0												
OF_0030	Shirley Street Pond	0												
OF_0031	Unnamed trib to Lake Quinsigamond	0												
OF_0032	Unnamed trib to Lake Quinsigamond	0												
OF_0033	Unnamed trib to Dean Park Pond	0												
OF_0034	Unnamed trib to Hop Brook crossing V	0												
OF_0035	Unnamed trib to Lake Quinsigamond	0												
OF_0036	Unnamed trib to Lake Quinsigamond	0												
OF_0037	Shirley Street Pond	0												
OF_0038	Unnamed trib to Lake Quinsigamond	0												
OF_0039	Unnamed trib to Rawson Hill Brook	0												
OF_0040	Unnamed to Rawson Hill Brook	0												
OF_0041	Shirley Street Pond	0												
OF_0042	Unnamed trib crossing Floral St	0												
OF_0043	Hop Brook	0												
OF_0044	Unnamed trib to West Brook	0												
OF_0045	Unnamed trib to Dean Park Pond	0												
OF_0046	Unnamed trib to Lake Quinsigamond	0												
OF_0047	Unnamed trib to Hop Brook	0												

	Last Updated: DRAFT					Table 7-1 Outfal		charge Detection a	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
			0 110	0 110	0 110	0 110	0 110	0 110	0 110	0 110	0 110	0 110	0 110	0 110
OF_0048	Unnamed trib to Lake Quinsigamond	0												
OF_0049	Unnnamed trib to Lake Quinsigamond	0												
OF_0050	Unnamed trib to Lake Quinsigamond	0												
OF_0051	Unnamed trib to Lake Quinsigamond	0												
OF_0052	Unnamed trib to Lake Quinsigamond	0												
OF_0053	Unnamed trib to Rawson Hill Brook	0												
OF_0054	Unnamed trib to Rawson Hill Brook	0												
OF_0055	Hop Brook	0												
OF_0056	Unnamed trib to Lake Quinsigamond	0												
OF_0057	Unnamed trib to West Brook W of Wes	0												
OF_0058	Unnamed trib to Hop Brook	0												
OF_0059	Unnamed trib to Bummet Brook - Smit	0												
OF_0060	Unnamed trib to wetland to Assabet R	0												
OF_0061	Unnamed trib to Hop Brook S of Main	0												
OF_0062	Unnamed trib to Summet Brook	0												
OF_0063	Unnamed trib to Eaton Pond	0												
OF_0064	Dean Park Pond	0												
OF_0065	Hop Brook	0												
OF_0066	Dean Park Pond	0												
OF_0067	Unnamed trib to Hop Brook crossing F	0												
OF_0068	Unnamed trib to Hop Brook crossing F	0												
OF_0069	Unnamed trib crossing Floral St	0												
OF_0070	Unnamed trib to West Brook	0												
OF_0071	Rawson Hill Brook	0												
OF_0072	Unnamed trib to Hop Brook S of Main	0												
OF_0073 OF_0074	Unnamed trib to Big Bummet Brook Unnamed trib to Big Bummet Brook	0												
OF_0074	Unnamed trib to Hop Brook	0												
OF_0076	Unnamed trib to Big Bummet Brook	0												
OF_0077	Unnamed trib to Big Bummet Brook	0												
OF_0078	Unnamed trib to Big Bummet Brook	0												
OF_0079	Unnamed trib to Big Bummet Brook	0												
OF_0080	Newton Pond Stream	0												
OF_0081	West Brook	0												
OF_0082	Rawson Hill Brook	0												
OF_0083	Unnamed trib to Mill Pond	0												
OF_0084	Shirley Street Pond	0												
OF_0085	Unnamed trib to Hop Brook crossing F	0												
OF_0086	Lake Quinsigamond	0												
OF_0087	Lake Quinsigamond	0												
OF_0088	Lake Quinsigamond	0												
OF_0089	Lake Quinsigamond	0												
OF_0090	Lake Quinsigamond	0												
OF_0091	Lake Quinsigamond	0												
OF_0092	Lake Quinsigamond	0												
OF_0093	Lake Quinsigamond	0												
OF_0094	Flint Pond (N.B.)	0												

	Last Updated: DRAFT					Table 7-1 Outfal		charge Detection	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF_0095	Flint Pond (N.B.)	0												
OF_0095 OF_0096	Flint Pond (N.B.)	0												
OF_0097	Lake Quinsigamond	0												
OF_0097 OF_0098	Lake Quinsigamond	0												
OF_0099	Flint Pond (N.B.)	0												
OF_0099 OF_0100	Flint Pond (N.B.)	0												
OF_0100	Flint Pond (N.B.)	0												
OF_0102	Flint Pond (S.B.)	0												
OF_0103	Flint Pond (S.B.)	0												
OF_0104	Flint Pond (S.B.)	0												
OF_0105	Lake Quinsigamond	0												
OF_0106	Flint Pond (S.B.)	0												
OF_0107	Flint Pond (S.B.)	0												
OF_0108	Flint Pond (S.B.)	0												
OF_0109	Flint Pond (S.B.)	0												
OF_0110	Flint Pond (S.B.)	0												
OF_0111	Flint Pond (S.B.)	0												
OF_0112	Flint Pond (N.B.)	0												
OF_0113	Flint Pond (N.B.)	0												
OF_0113	Flint Pond (N.B.)	0												
OF_0114 OF_0115	Flint Pond (N.B.)	0												
OF_0116	Flint Pond (N.B.)	0												
OF_0117		0												
OF_0117 OF_0118	Lake Quinsigamond Lake Quinsigamond	0												
OF_0119	Lake Quinsigamond	0												
OF_0120	Lake Quinsigamond	0												
OF_0121	Lake Quinsigamond	0												
OF_0122	Lake Quinsigamond	0												
OF_0123	Lake Quinsigamond	0												
OF_0124	Lake Quinsigamond	0												
OF_0125	Lake Quinsigamond	0												
OF_0126	Lake Quinsigamond	0												
OF_0127	Lake Quinsigamond	0												
OF_0128	Lake Quinsigamond	0												
OF_0129	Lake Quinsigamond	0												
OF_0130	Lake Quinsigamond	0												
OF_0131	Lake Quinsigamond	0												
OF_0132	Lake Quinsigamond	0												
OF_0133	Lake Quinsigamond	0												
OF_0134	Lake Quinsigamond	0												
OF_0135	Lake Quinsigamond	0												
OF_0136	Lake Quinsigamond	0												
OF_0137	Lake Quinsigamond	0												
OF_0138	Lake Quinsigamond	0												
OF_0138	Lake Quinsigamond	0												
OF_0139 OF_0140	Lake Quinsigamond	0												
OF_0140	Lake Quinsigamond	0												

	Last Updated: DRAFT					Table 7-1 Outfa		charge Detection	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF_0142	Lake Quinsigamond	0												
OF_0143	Unnamed trib to Hop Brook S of Main	0												
OF_0144	Unnamed trib crossing Floral St	0												
OF_0145	Unnamed trib to Hop Brook S of Main	0												
OF_0146	Unnamed trib to Meadow Brook E of C	0												
OF_0147	Unnamed trib to Meadow Brook E of C	0												
OF_0148	Unnamed trib to wetland to Assabet R	0												
OF_0149	Little Bummet Brook	0												
OF_0150	Unnamed trib to Hop Brook S of Main	0												
OF_0151	Unnamed trib to Hop Brook S of Main	0												
OF_0152	Unnamed trib to Hop Brook S of Main	0												
OF_0153	Unnamed trib to Hop Brook S of Main	0												
OF_0154	Unnamed trib to Hop Brook S of Main	0												
OF_0155	Unnamed trib to Hop Brook S of Main	0												
OF_0156	Unnamed trib to Hop Brook S of Main	0												
OF_0157	Unnamed trib to Eaton Pond	0												
OF_0158	Unnamed trib to Meadow Brook at Edg	0												
OF_0159	Shirley Street Pond	0												
OF_0160	Rawson Hill Brook	0												
OF_0161	Unnamed trib to Big Bummet Brook	0												
OF_0162	Unnamed trib to West Brook	0												
OF_0163	Unnamed trib to West Brook	0												
OF_0164	Unnamed trib to West Brook	0												
OF_0165	Unnamed to Rawson Hill Brook	0												
OF_0166	Unnamed trib to Rawson Hill Brook	0												
OF_0167	Newton Pond	0												
OF_0168	Unnamed trib to Newton Pond	0												
OF_0169	Unnamed trib to Rawson Hill Brook	0												
OF_0170	Unnamed trib to Rawson Hill Brook	0												
OF_0171	Rawson Hill Brook	0												
OF_0172	Meadow Brook	0												
OF_0173	Meadow Brook	0												
OF_0174	Meadow Brook	0												
OF_0175	Unnamed trib to Meadow Brook	0												
OF_0176	Meadow Brook	0												
OF_0177	Unnamed trib to Meadow Brook	0												
OF_0178	Unnamed trib to Rawson Hill Brook	0												
OF_0179	Unnamed trib to West Brook	0												
OF_0180	Unnamed trib to West Brook	0												
OF_0180	Unnamed trib to West Brook	0												
OF_0181	Unnamed trib to West Brook W of West	0												
OF_0182	Unnamed trib to West Brook	0												
OF_0183	Unnamed trib to Big Bummet Brook	0												
OF_0185	Unnamed trib to Lake Quinsigamond	0												
OF_0186	Unnamed trib to Lake Quinsigamond	0												
	-													
OF_0187	Unnamed trib to Lake Quinsigamond	0												
OF_0188	Unnamed trib to Lake Quinsigamond	0	1											

	Last Updated: DRAFT					Table 7-1 Outfa		charge Detection a	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF_0189	Unnamed trib to Lake Quinsigamond	0												
OF_0190	Unnamed trib to Little Bummet Brook a	0												
OF_0191	Unnamed trib to Little Bummet Brook a	0												
OF_0192	Unnamed trib to Hop Brook	0												
OF_0193	Unnamed trib to Bummet Brook N of T	0												
OF_0194	Unnamed trib to Big Bummet Brook	0												
OF_0195	Unnamed trib to Hop Brook	0												
OF_0196	Unnamed trib to Bummet Brook - Smit	0												
OF_0197	Unnamed trib to Bummet Brook - Smit	0												
OF_0198	Unnamed trib to Bummet Brook - Smit	0												
OF_0199	Unnamed trib to Bummet Brook - Smit	0												
OF_0200	Rawson Hill Brook	0												
OF_0201	Unnamed trib to West Brook	0												
OF_0202	Unnamed trib to West Brook	0												
OF_0203	Unnamed trib to West Brook	0												
OF_0204	Unnamed trib to West Brook	0												
OF_0205	Unnamed trib to West Brook	0												
OF_0206	Unnamed trib to West Brook	0												
OF_0207	Unnamed trib to West Brook	0												
OF_0208	Unnamed trib to Flint Pond (N.B.)	0												
OF_0209	Unnamed trib to Big Bummet Brook	0												
OF_0210	Unnamed trib to Big Bummet Brook	0												
OF_0211	Unnamed trib to Big Bummet Brook	0												
OF_0212	Unnamed trib to Big Bummet Brook	0												
OF_0213	Unnamed trib to Little Bummet Brook	0												
OF_0214	Unnamed trib to Mill Pond	0												
OF_0215	Unnamed trib to Big Bummet Brook	0												
OF_0216	Unnamed trib to Big Bummet Brook	0												
OF_0217	Unnamed trib to Hop Brook	0												
OF_0218	Rawson Hill Brook	0												
OF_0219	Rawson Hill Brook	0												
OF_0220	Unnamed trib to Dean Park Pond	0												
OF_0221	Unnamed trib to Hop Brook	0												
OF_0222	Unnamed trib W of South St	0												
OF_0223	Unnamed trib W of South St	0												
OF_0224	Unnamed trib to Flint Pond (N.B.)	0												
OF_0225	Unnamed trib to Meadow Brook	0												
OF_0226	Meadow Brook	0												
OF_0227	Meadow Brook	0												
OF_0228	West Brook	0												
OF_0229	Mill Pond	0												
OF_0230	Unnamed trib to Mill Pond	0												
OF_0231	Unnamed trib to Mill Pond	0												
OF_0232	Unnamed trib to West Brook	0												
OF_0233	Unnamed trib to Meadow Brook	0												
OF_0234	Unnamed trib to Meadow Brook	0												
OF_0235	Unnamed trib to Big Bummet Brook	0												

	Last Updated: DRAFT					Table 7-1 Outfal		as part charge Detection a	ctor (SVF) Invento t of the and Elimination (ID OccumentCenter/V		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF_0236	Unnamed trib to Big Bummet Brook	0												
OF_0237	Unnamed trib to Big Bummet Brook	0												
OF_0238	Mill Pond	0												
OF_0239	Mill Pond	0												
OF_0240	Mill Pond	0												
OF_0241	Unnamed trib to Little Bummet Brook f	0												
OF_0242	Unnamed trib to Big Bummet Brook E	0												
OF_0243	Unnamed trib to Big Bummet Brook E	0												
OF_0244	Unnamed trib to Little Bummet Brook I	0												
OF_0245	Unnamed trib to Little Bummet Brook f	0												
OF_0246	Unnamed trib to Little Bummet Brook I	0												
OF_0247	Unnamed trib to Little Bummet Brook f	0												
OF_0248	Unnamed trib to Big Bummet Brook	0												
OF_0249	Unnamed trib to Big Bummet Brook	0												
OF_0250	Unnamed trib to Big Bummet Brook	0												
OF_0251	Unnamed trib to Big Bummet Brook	0												
OF_0252	Unnamed trib to Big Bummet Brook	0												
OF_0253	Unnamed trib to Big Bummet Brook	0												
OF_0254	Unnamed trib to Big Bummet Brook	0												
OF_0255	Unnamed trib to Big Bummet Brook	0												
OF_0256	Unnamed trib to Big Bummet Brook	0												
OF_0257	Unnamed trib to Meadow Brook	0												
OF_0258	Unnamed trib to Hop Brook crossing V	0												
OF_0259	Unnamed trib to Hop Brook crossing V	0												
OF_0260	Unnamed trib W of South St	0												
OF_0261	Unnamed trib W of South St	0												
OF_0262	Unnamed trib W of South St	0												
OF_0263	Unnamed trib W of South St	0												
OF_0264	Unnamed trib to Big Bummet Brook	0												
OF_0265	Unnamed trib to Big Bummet Brook	0												
OF_0266	Unnamed trib to Hop Brook E of Franc	0												
OF_0267	Unnamed trib to Hop Brook E of Franc	0												
OF_0268	Unnamed trib to Hop Brook E of Franc	0												
OF_0269	Unnamed trib to Hop Brook E of Franc	0												
OF_0270	Unnamed trib to Hop Brook E of Franc	0												
OF_0271	Unnamed trib to Hop Brook E of Franc	0												
OF_0272	Unnamed trib to Hop Brook E of Franc	0												
OF_0273	Unnamed trib to Hop Brook E of Franc	0												
OF_0274	Unnamed trib to Lake Quinsigamond	0												
OF_0275	Unnamed trib to Lake Quinsigamond	0												
OF_0276	Unnamed trib to Lake Quinsigamond	0												
OF_0277	Unnamed trib to Meadow Brook E of C	0												
OF_0278	Unnamed trib to Big Bummet Brook	0												
OF_0279	Unnamed trib to Hop Brook E of Franc	0												
OF_0280	Unnamed trib to Hop Brook	0												
OF_0281	Unnamed trib to Hop Brook	0												
OF_0282	Unnamed trib to Hop Brook	0												

	Last Updated: DRAFT					Table 7-1 Outfa		em Vulnerability Fa as part scharge Detection a prewsburyma.gov/l	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF_0283	Unnamed trib to Flint Pond (N.B.)	0												
OF_0284	Unnamed trib to Big Bummet Brook	0												
OF_0285	Unnamed trib to Big Bummet Brook	0												
OF_0286	Unnamed trib to Flint Pond (N.B.)	0												
OF_0287	Unnamed trib to Meadow Brook E of C													
OF_0288	Unnamed trib to Meadow Brook E of C													
OF_0289	Unnamed trib to Meadow Brook	0												
OF_0290	Unnamed trib to Worc Sand -Shirley S													
OF_0291	Unnamed trib to Eaton Pond	0												
OF_0292	Unnamed trib to Hop Brook	0												
OF_0293	Unnamed trib to Hop Brook	0												
OF_0294	Unnamed trib to Eaton Pond E of Sene	0												
OF_0295	Unnamed trib to Hop Brook W of Sout													
OF_0296	Unnamed trib to Hop Brook W of Soutl	0												
OF_0297	Unnamed trib to Hop Brook W of Sout													
OF_0298	Unnamed trib to Hop Brook W of Sout	0												
OF_0299	Unnamed trib to Hop Brook W of Sout													
OF_0300	Unnamed trib to Big Bummet Brook	0												
OF_0301	Unnamed trib W of South St	0												
OF_0302	Unnamed trib to Big Bummet Brook	0												
OF_0303	Unnamed trib W of South St	0												
OF_0304	Unnamed trib to Big Bummet Brook	0												
OF_0305	Unnamed trib W of South St	0												
OF_0306	Unnamed trib to Big Bummet Brook	0												
OF_0307	Unnamed trib to Big Bummet Brook	0												
OF_0308	Unnamed trib to Hop Brook S of Main	0												
OF_0309	Unnamed trib to Hop Brook S of Main	0												
OF_0310	Unnamed trib to West Brook	0												
OF_0311	Shirley Street Pond	0												
OF_0312	Shirley Street Pond	0												
OF_0313	Unknown - Isolated	0												
OF_0314	Unnamed trib to Hop Brook	0												
OF_0315	Unnamed trib to Rawson Hill Brook	0												
OF_0316	Dean Park Pond	0												
OF_0317	Unnamed trib to Meadow Brook	0												
OF_0318	Unnamed trib to Meadow Brook	0												
OF_0319	Unnamed trib to Rawson Hill Brook	0												
OF_0320	Unnamed trib to Meadow Brook	0												
OF_0321	Unnamed trib to Meadow Brook	0												
OF_0322	Unnamed trib to Hop Brook	0												
OF_0323	Unnamed trib to Big Bummet Brook	0												
OF_0324	West Brook	0												
OF_0325	Unnamed trib to West Brook	0												
OF_0326	Unnamed trib to Hop Brook S of Main	0												
OF_0327	Unnamed trib crossing Floral St	0												
OF_0328	Unnamed trib crossing Floral St	0												
OF_0329	Unnamed trib to Hop Brook crossing F	0												

	Last Updated: DRAFT					Table 7-1 Outfal		em Vulnerability Fa as par scharge Detection a prewsburyma.gov/l	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
05.000														
OF_0330	Unnamed trib to West Brook	0												
OF_0331	Unnamed trib to Newton Pond	0												
OF_0332	Unnamed trib to Newton Pond	0												
OF_0333	Unnamed trib to Newton Pond	0												
OF_0334	Unnamed trib to Newton Pond	0												
OF_0335	Unnamed trib to Big Bummet Brook	0												
OF_0336	Unnamed trib to Hop Brook	0												
OF_0337	Unnamed trib to Hop Brook	0												
OF_0338	Hop Brook	0												
OF_0339	Unnamed trib to Worc Sand -Shirley S	0												
OF_0340	Unnamed trib to Flint Pond (N.B.)	0												
OF_0341	Unnamed trib to Flint Pond (N.B.)	0												
OF_0342	Unnamed trib to Flint Pond (N.B.)	0												
OF_0343	Unnamed trib to Mill Pond	0												
OF_0344	Unnamed trib to West Brook	0												
OF_0345	Unnamed trib to Rawson Hill Brook	0												
OF_0346	Unnamed trib to Rawson Hill Brook	0												
OF_0347	Unnamed trib to Rawson Hill Brook	0												
OF_0348	West Brook	0												
OF_0349	Unnamed trib to Meadow Brook	0												
OF_0350	Unnmaed trib to Meadow Brook	0												
OF_0351	Newton Pond	0												
OF_0352	Mud Pond	0												
OF_0353	Unnamed trib to Worc Sand -Shirley S	0												
OF_0354	Unnamed trib to Worc Sand -Shirley S	0												
OF_0355	Unnamed trib to Meadow Brook E of C	0												
OF_0356	Unnamed trib E of Crescent St	0												
OF_0357	Unnamed trib E of Crescent St	0												
OF_0358	Unnamed trib to Meadow Brook	0												
OF_0359	Unnamed trib to Hop Brook S of Main	0												
OF_0360	Unnamed trib to S of Main Blvd	0												
OF_0361	West Brook	0												
OF_0362	Unnamed trib to Meadow Brook	0												
OF_0363	Unnamed trib to Jordan Pond	0												
OF_0364	Unnamed trib to Lake Quinsigamond	0												
OF_0365	Unnamed trib to Lake Quinsigamond	0												
OF_0366	Unnamed trib to Lake Quinsigamond	0												
OF_0367	Unnamed trib to Lake Quinsigamond	0												
OF_0368	Meadow Brook	0												
OF_0369	Unnamed trib to Big Bummet Brook	0												
OF_0370	Unnamed trib to Big Bummet Brook	0												
OF_0371	Unnamed trib to Big Bummet Brook E	0												
OF_0372	Unnamed trib to Big Bummet Brook	0												
OF_0373	Unnamed trib to Flint Pond (N.B.)	0												
OF_0374	Unnamed trib to Big Bummet Brook E	0												
OF_0375	Unnamed trib to Big Bummet Brook E	0												
OF_0376	Unnamed trib to Big Bummet Brook E	0												

	Last Updated: DRAFT					Table 7-1 Outfa		em Vulnerability Fa as part scharge Detection a prewsburyma.gov/l	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF 0277	Unnamed trib to Flint Pond (N.B.)	0												
OF_0377 OF_0378	Unnamed trib to Flint Pond (N.B.)	0												
OF_0378	Unnamed trib to Flint Pond (N.B.)	0												
OF_0379 OF_0380	Unnamed trib to Flint Pond (N.B.)	0												
OF_0381	Unnamed trib to Flint Pond (N.B.)	0												
OF_0382	Unnamed trib to Flint Pond (N.B.)	0												
OF_0383	Unnamed trib to Flint Pond (N.B.)	0												
OF_0384	Unnamed trib to Flint Pond (N.B.)	0												
OF_0385	Unnamed trib to Flint Pond (N.B.)	0												
OF_0386	Unnamed trib to Meadow Brook	0												
OF_0387	Unnamed trib to Meadow Brook	0												
OF_0388	Meadow Brook	0												
	Unnamed trib to Meadow Brook	0												
OF_0389	Unnamed trib to Flint Pond (N.B.)	0												
OF_0390 OF_0391	Unnamed trib to Flint Pond (N.B.)	0												
_		0												
OF_0392	Unnamed trib to Flint Pond (N.B.)	0												
OF_0393	Unnamed trib to Summet Brook													
OF_0394	Unnamed trib to Summet Brook	0												
OF_0395	Unnamed trib to Summet Brook	0												
OF_0396	Unnamed trib to Summet Brook	0												
OF_0397	Summet Brook	0												
OF_0398	Summet Brook	0												
OF_0399	Unnamed trib to Little Bummet Brook I	0												
OF_0400	Unnamed trib to Little Bummet Brook (0												
OF_0401	Unnamed trib to Little Bummet Brook (0												
OF_0402	Unnamed trib to Little Bummet Brook I	0												
OF_0403	Unnamed trib to Little Bummet Brook I	0												
OF_0404	Unnamed trib to Little Bummet Brook I	0												
OF_0405	Unnamed trib to Little Bummet Brook I	0												
OF_0406	Unnamed trib to Little Bummet Brook I	0												
OF_0407	Unnamed trib to wetland to Assabet R	0												
OF_0408	Unnamed trib to wetland to Assabet R	0												
OF_0409	Unnamed trib to wetland to Assabet R	0												
OF_0410	Unnamed trib to wetland to Assabet R	0												
OF_0411	Unnamed trib to wetland to Assabet R	0												
OF_0412	Unnamed trib to wetland to Assabet R	0												
OF_0413	Unnamed trib to wetland to Assabet R	0												
OF_0414	Unnamed trib to Big Bummet Brook	0												
OF_0415	Unnamed trib to Big Bummet Brook	0												
OF_0416	Unnamed trib to West Brook	0												
OF_0417	Unnamed trib to Big Bummet Brook	0												
OF_0418	Unnamed trib to Big Bummet Brook	0												
OF_0419	Unnamed trib to Hop Brook	0												
OF_0420	Unnamed trib to Hop Brook	0												
OF_0421	Dean Park Pond	0												
OF_0422	Unnamed trib to Hop Brook	0												
OF_0423	Unnamed trib to Hop Brook	0												

	Last Updated: DRAFT					Table 7-1 Outfal		charge Detection	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
05.0101														
OF_0424	Unnamed trib to Big Bummet Brook	0												
OF_0425	Unnamed trib to Big Bummet Brook	0												
OF_0426	Unnamed trib to West Brook	0												
OF_0427	Unnamed trib to West Brook	0												
OF_0428	Unnamed trib to West Brook	0												
OF_0429	Unnamed trib to West Brook	0												
OF_0430	Unnamed trib to West Brook	0												
OF_0431	Unnamed trib to West Brook	0												
OF_0432	Unnamed trib to Rawson Hill Brook	0												
OF_0433	Unnamed trib to West Brook	0												
OF_0434	Rawson Hill Brook	0												
OF_0435	Unnamed trib to Dean Park Pond	0												
OF_0436	Unnamed trib to Dean Park Pond	0												
OF_0437	Unnamed trib to Dean Park Pond	0												
OF_0438	Unnamed trib to Dean Park Pond	0												
OF_0439	Unnamed trib to Dean Park Pond	0												
OF_0440	Unnamed trib to Dean Park Pond	0												
OF_0441	Unnamed trib to Dean Park Pond	0												
OF_0442	Hop Brook	0												
OF_0443	Hop Brook	0												
OF_0444	Dean Park Pond	0												
OF_0445	Hop Brook	0												
OF_0446	Hop Brook	0												
OF_0447	Unnamed trib to Hop Brook E of Bonni	0												
OF_0448	Hop Brook	0												
OF_0449	Hop Brook	0												
OF_0450	Hop Brook	0												
OF_0451	Unnamed trib to Hop Brook	0												
OF_0452	Unnamed trib to Hop Brook	0												
OF_0453	Unnamed trib to Hop Brook - N of Mair	0												
OF_0454	Unnamed trib to Hop Brook	0												
OF_0455	Unnamed trib to Hop Brook	0												
OF_0456	Unnamed trib to Rawson Hill Brook	0												
OF_0457	Unnamed trib to Rawson Hill Brook	0												
OF_0458	Unnamed trib to Hop Brook	0												
OF_0459	Unnamed trib to West Brook	0												
OF_0460	Rawson Hill Brook	0												
OF_0461	Rawson Hill Brook	0												
OF_0462	Unnamed trib to Rawson Hill Brook	0												
OF_0463	Unnamed trib to Rawson Hill Brook	0												
OF_0464	Unnamed trib to Rawson Hill Brook	0												
OF_0465	Unnamed trib to Rawson Hill Brook	0												
OF_0466	Unnamed trib to Rawson Hill Brook	0												
OF_0467	Unnamed trib to Rawson Hill Brook	0												
OF_0468	Unnamed trib to Rawson Hill Brook	0												
OF_0469	Unnamed trib to Rawson Hill Brook	0												
OF_0470	Unnamed trib to Hop Brook	0												

	Last Updated: DRAFT					Table 7-1 Outfal		em Vulnerability Fa as part charge Detection a rewsburyma.gov/l	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
		_												
OF_0471	Unnamed trib to Hop Brook	0												
OF_0472	Unnamed trib to Hop Brook	0												
OF_0473	Unnamed trib to Hop Brook	0												
OF_0474	Unnamed trib to Hop Brook	0												
OF_0475	Unnamed trib to Hop Brook													
OF_0476	Unnamed trib to Hop Brook	0												
OF_0477	Unnamed trib to Hop Brook	0												
OF_0478	Unnamed trib to Hop Brook	0												
OF_0479	Unnamed trib to Hop Brook	0												
OF_0480	Unnamed trib to Hop Brook	0												
OF_0481	Unnamed trib to Hop Brook	0												
OF_0482	Unnamed trib to Hop Brook	0												
OF_0483	Unnamed trib to Hop Brook	0												
OF_0484	Unnamed trib to Hop Brook	0												
OF_0485	Unnamed trib to Hop Brook	0												
OF_0486	Unnamed trib to Hop Brook	0												
OF_0487	Unnamed trib to Hop Brook	0												
OF_0488	Unnamed trib to Rawson Hill Brook	0												
OF_0489	Unnamed trib to Rawson Hill Brook	0												
OF_0490	Unnamed trib to Northboro Reservoir	0												
OF_0491	Unnamed trib to Hop Brook	0												
OF_0492	Unnamed trib to Hop Brook	0												
OF_0493	Unnamed trib to Rawson Hill Brook	0												
OF_0494	Rawson Hill Brook	0												
OF_0495	Rawson Hill Brook	0												
OF_0496	Rawson Hill Brook	0												
OF_0497	Rawson Hill Brook	0												
OF_0498	Rawson Hill Brook	0												
OF_0499	Rawson Hill Brook	0												
OF_0500	Rawson Hill Brook	0												
OF_0501	Rawson Hill Brook	0												
OF_0502	Unnamed to Rawson Hill Brook	0												
OF_0503	Rawson Hill Brook	0												
OF_0504	Unnamed to Rawson Hill Brook	0												
OF_0505	Rawson Hill Brook	0												
OF_0506	Rawson Hill Brook	0												
OF_0507	Unnamed to Rawson Hill Brook	0												
OF_0508	Unnamed to Rawson Hill Brook	0												
OF_0509	Rawson Hill Brook	0												
OF_0510	Rawson Hill Brook	0												
OF_0511	Rawson Hill Brook	0												
OF_0512	Rawson Hill Brook	0												
OF_0513	Rawson Hill Brook	0												
OF_0514	Rawson Hill Brook	0												
OF_0515	Rawson Hill Brook	0												
OF_0516	Rawson Hill Brook	0												
OF_0517	Unnamed trib to Rawson Hill Brook	0												

	Last Updated: DRAFT					Table 7-1 Outfal		em Vulnerability Fa as par scharge Detection prewsburyma.gov/	t of the		y, Massachusetts			
Outfall ID	Receiving Water	Score	History of SSOs [1]	Common or Twin Invert Manholes [2]	Common Trench Construction	Storm/Sanitary Sewer Crossings (Sanitary Above)	Sanitary Lines	Inadequate	Areas Formerly Served by Combined Sewers [3]	Sanitary Infrastructure Defects	SSO Potential In Event of System Failures	Sanitary and Storm Drain Infrastructure > 40 y/o	Septic with Poor Soils or Water Table Separation	History of BOH Actions Addressing Septic Failure
	Scoring Criteria		1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No	1 = Yes 0 = No
OF_0518	Unnamed trib to Rawson Hill Brook	0												
OF_0519	Unnamed trib to Rawson Hill Brook	0												
OF_0520	Unnamed trib to Rawson Hill Brook	0												
OF_0521	Jordan Pond	0												
OF_0522	Jordan Pond	0												

- [1] History of SSOs, including, but not limited to, those resulting from wet weather, high water table, or fat/oil/grease blockages.
- [2] Common or twin-invert manholes serving storm and sanitary sewer alignment
- [3] DNA in Shrewsbury